

R94-R792

Scan left .0065

Trigger adjusting screw has been
re-set - Trig pull - ~~35.4~~ lbs.
35.4

Other screws OK