

RECEIVING AND ESTIMATING REPORT

CUST NO: 046572 ILION		COMMENTS WEATHERBY					
INITIAL LCS	CUSTOMER ORDER NO.						
DATE RECEIVED 07/18/91	DATE OPENED 07/23/91	DATE CODE AK 3-90	SERIAL NUMBER C6521887	MODEL AND GRADE 700 300 AS/MAG		ORDER R 91-1431	
ACCESSORIES W/STUDS		L/SIGHTS					

FROM: [RODGERS, TERRY RT 2 BOX 531B LA FAYETTE GA 30728 USA	SHIP TO: [RODGERS, TERRY RT 2 BOX 531B LA FAYETTE GA USA 30728
---	--

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE <input type="checkbox"/>	CLEAN/TEST	PROM. DATE	ESTIMATED 8-9-91	VIA UPS
----------------	--------------------	--------------------------------	------------	------------	---------------------	------------

REPAIR CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL
---------------	-----	-----------	-----	-------------	-------

GUN CONDITION: NEW SLIGHTLY WORN VERY WORN MISUSED MARRED

CUSTOMER'S REQUEST
Firing pic falls when you close bolt, sometimes when you push safety off.

MAIN FAULT
Trigger assembly rusted from unknown source - internal parts of assembly are not moving freely - rifle would not cock to receive.

PARTS

- 1) replace trigger assembly at no charge, as gesture of good-will. - 4 pound per request.
- 2) Have rifle shot in gallery to check for accuracy.

REPAIRMAN <i>DE</i>	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 7/90