

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER
R 94-12026INITIAL
FJR

CUSTOMER ORDER NO.

DATE RECEIVED
04/04/94DATE OPENED
04/06/94DATE CODE
ES 10-69SERIAL NUMBER
6267098

NEW SERIAL NUMBER

MODEL AND GRADE
700 308

ADL

ACCESSORIES

W/STUDS

SCOPE BASE

FROM:

ROOT, E A (ARNIE)
615 E 5TH ST
LADYSMITH

WI 54848

SHIP TO:

ROOT, E A (ARNIE)
615 E 5TH ST
LADYSMITHWI
54848

CUST NO: 095418 C.D.D.L

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

WRITE ☐

PROM. DATE

ESTIMATED

VIA

UPS

GUN CONDITION

- ☐ NEW
☐ LIGHTLY WORN
☐ WORN
☐ VERY WORN
☐ UNREPAIRABLE
☐ MARRED

Product Service

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP		B2			E1	E1
BOLT ASSY.		B3			E2	E2
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.		B5				
WOOD			C1	D3	E5	F5
METAL			C2			

MAIN FAULT

Upon receipt, we could not duplicate the customer's concern.
However, examination revealed that trigger housing and action bar safety, both of
which dropping out with lubrication. But the spring in action bar and mag.
spring. Light mag. spring. Both mag. 909

PARTS

Trigger Rod 4 1/4 lb.
Gun Bolt .007
#20345 Trigger Spring

COMMENTS

Replaced Trigger Spring with
V. Clean action at 1/2 normal spring
cost; as per order of good will.

REMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

RD6925 REV. 1/94