

SENTRY INSURANCE

March 29, 1994

Service Dept.
Remington Arms Co. Inc.
14 Hoefler Ave.
Lebanon, N.Y. 13357

Dear Service Dept;

As per phone instructions I am returning
this model 700 rifle to you for repair.

The rifle will fire without pulling the
trigger, when the safety is moved to "fire"
position.

I thank you for your attention.

Sincerely,
Arnie Root



E. A. (ARNIE) ROOT
615 E. 5th Street
Ladysmith, Wisconsin 54848
Phone: 532-~~6577~~ 3498