

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER
R 92-25724

DATE RECEIVED 11/23/92	DATE OPENED 12/01/92	DATE CODE LQ 2-78	SERIAL NUMBER A6564027	NEW SERIAL NUMBER	MODEL AND GRADE 700 270	BDL
ACCESSORIES SLING STRAP W/STUDS W/SWIVELS						

FROM: SCHMIDT, PATRICK A
3241 JACKS RUN RD
WHITE OAK PA 15131

SHIP TO: SCHMIDT, PATRICK A
3241 JACKS RUN RD
WHITE OAK PA 15131

CUST NO: 070919 C-D-DL

COUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐ CLEAN/TEST	FROM DATE	ESTIMATED	VIA UPS
V CONDITION NEW LIGHTLY WORN WORN VERY WORN UNREPAIRABLE MARRED					REPAIR CHARGE EXCISE TAX INSURANCE UPS PARCEL POST TOTAL

STOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CLE	A1	B1				
GGER GROUP		B2			E1	F1
.T ASSY.		B3				F2
REL ASSY.		B4		DY	E3	F3
. ASSY.		B5		D2	E4	F4
DD			C1	D3	E5	F5
AL			C2			

FAULT: Could not duplicate Condition Customer described. However, disassembly revealed that a gummy substance was found on the trigger assembly, it stop Rpt. mfg. 1978. Cleaning required.

After pull 5 1/2 pounds, run - left .007

COMMENTS: Based on study / gummy condition of trigger assembly, replaced trigger assembly at 1/2 normal cost, as gesture of good will. Customer has authorized repair under \$50.00 per letter. Approved 12/29/92 per phone

REPAIRMAN B W	PROOF	CLEAN ☒	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

REV. 1/92