

*Custom Complaint*P.I. NO GUN EXAMINATION REPORT NUMBER: _____ MODEL: (660)GENERAL CONDITION: NEW R #: 010974OUTSIDE WORK: NO DATE: 5-16-72FROM: SCHNEIDER'SFIRED AMMO TYPE: — LONGVIEW, WASH.& CONDITION: _____ GUN #: 115110PROOF: R.E.P. ^{ASSEMBLER 83} INSP.: 11 TEST: 13 CODE: OR = 7/68HEADING: O.K. GR./CAL.: 243BREECH OPENING: _____ CHECKED BY: G. PROSSERRECOIL SHOULDERS: O.K. APPROVED: _____CHAMBER: O.K. APPROVED: _____TEST: NO APPROVED: _____

COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

NO BROKEN COMPONENTSCOMPLAINT: WONT COCKINCIDENT: FOLLOWS DOWN.COMMENTS: APPARENTLY DIRT BETWEEN TRIGGER AND INSIDE OF
HOUSING (TRIGGER & CONNECTOR LAY TO THE LEFT) CAUSED THE
TRIGGER TO STICK IN FIRED POSITION.