

ANCER.

235 W. Turbo
San Antonio, TX 78216
(025)

15042 Parkway Loop
Suite D
Tustin, CA 92680
(901)

339 N. Oakley
Chicago, IL 60612
(902)

1349 Old 41 HWY.
Suite 215
Marietta, GA 30060
(904)

ACCT #

ORDER #

SOLD TO:

Eng. Dept

SHIP TO:

*Remington Arms Service
14 Hefley Avenue
Union, NY 13357*

ORDER DATE	SALESMAN	REQ. DEL. DATE	CUSTOMER P.O.#	SHIP VIA	COL	PPD	PPD ADD	COD
4/7/90		4/16/90		Reg UPS		✓		
QTY ORD.	PART NO.	DESCRIPTION	WHS #	UNIT PRICE	EXTEN.	SCHED. SHIP DATE		
1		Remington Model 700 Serial No A6619669		N/C				
		For repair - the gun discharged when the bolt is locked forward with chambering a round.						
		Return To:						
		George Schroeder						
		235 W. TURBO						
		San Antonio TX 78216						
		PH: 1-800-729-1500						
ORDER TAKEN BY				TAX		TOTAL		
OUTBOUND FREIGHT CHGS.				WHT		PKGS		
INBOUND FREIGHT CHGS.				PACKED BY		SHIPPED BY		
TOTAL FREIGHT CHGS.				CARRIER		PRO #		
SIGNED <i>J. K...</i>				DATE <i>4-90-90</i>		PRO # <i>173 823 042</i>		