

REMINGTON NEW GUN REPAIR INVOICE

Remington Recommended Gunsmith
Name Allison & Carey Gun Works
Street 10218 S. E. Powell Blvd.
City Portland State Ore Zip 97266

Customer's Name Kenneth Scott
Street 533 Haussler Rd.
City Kelso State Wa Zip 98626

<u>Date Firearm Received</u> 9/12/79		<u>Date Returned to Customer</u> 6/20/80		<u>Returned to Factory</u>	
				<u>Date</u> 9/19/79	<u>Via</u> UPS
<u>Model</u> 700	<u>Cal. or Gauge</u> .243	<u>Grade</u>	<u>Serial Number</u> A6537563		

Complete Description of Customer's Complaint

Gun has fired when taken off safety. Customer was absolutely sure he did not have finger on the trigger.

Rifle was being held a PF SC for examination

Repairs Performed - Describe in detail

Sent to Remington Arms Service Section
Attn: Mr. Dennis Sanita
Received back from Remington UPS, after several letters and phone calls, 6/12/80/

Repair Charge Breakdown

Parts	\$	
Labor		20.00
Handling & packing Test Ammunition		4.50
Transportation		4.40
Total	\$	28.99

Approvals in order:

1. Field Representative

2. Regional Manager

3. Arms Service (2)

Date:

Date:

Date: