

RECEIVING AND ESTIMATING REPORT

COMMENTS

R 92-10617 ORDER

INITIAL
FPS

CUSTOMER ORDER NO.

ATTN: JIM STEKL

DATE RECEIVED
04/16/92DATE OPENED
04/27/92DATE CODE
PT 6-70SERIAL NUMBER
6347446

NEW SERIAL NUMBER

MODEL AND GRADE

700 6MM REM ADL

ACCESSORIES

W/STUDS

SCOPE BASE

L/SIGHTS

FROM:

SKUTTLE MFG CO
ATTN: MARTY HANSELL
RT 10
MARIETTA

OH 45750

SHIP TO:

SKUTTLE MFG CO
ATTN: MARTY HANSELL
RT 10
MARIETTAOH
45750

CUST NO: 061294 C.O.D

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

WRITE ☐

CLEAN/TEST

PROM. DATE

ESTIMATED

VIA

UPS

GUN CONDITION

- ☐ NEW
☐ LIGHTLY WORN
☐ WORN
☐ VERY WORN
☐ UNREPAIRABLE
☐ MARRED

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP	The rifle has been discharging upon bolt closure					
BOLT ASSY.		B3			E2	F2
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

MAIN FAULT

"The trigger pin will sometimes follow down when operating bolt assembly - trigger assembly has been adjusted out of factory - trigger pull measured at 24 pounds (well below my spec of 35) - trigger activation is not positive, due to this light pull."

See left - 010"

PARTS

COMMENTS

Offer to re-adjust present trigger assembly or, to replace trigger assembly at \$ nominal cost. As a gesture of good-will, if it were better to restore confidence in the rifle.

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

RD6925 REV. 1/5

PPS 04581