

RECEIVING AND ESTIMATING REPORT

COMMENTS

Product Service

ORDER
R 93-27219INITIAL
T INCUSTOMER ORDER NO.
315DATE RECEIVED
12/06/93DATE OPENED
12/14/93DATE CODE
PB 6-81SERIAL NUMBER
B6093628

NEW SERIAL NUMBER

MODEL AND GRADE
788 308

ACCESSORIES

L CLIP

W/STUDS

SCOPE BASE

FROM:

SOUTHWEST SHOOTERS SUPPLY
1940 LINWOOD BLVD
OKLAHOMA CITY OK 73106

SHIP TO:

SOUTHWEST SHOOTERS SUPPLY
1940 LINWOOD BLVD
OKLAHOMA CITY OK 73106

CUST NO:005284 WILM L

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

WRITE ☐

FROM DATE

ESTIMATED

VIA

UPS

GUN CONDITION

- ☐ NEW
☐ LIGHTLY WORN
☐ WORN
☐ VERY WORN
☐ UNREPAIRABLE
☐ MARRED

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN

AMMO

FUNCTION

FINISH

ACCURACY

FIT

INSPECT

CYCLE

A1

JP

TRIGGER GROUP

B1

BOLT ASSY.

B2

BARREL ASSY.

B3

REC. ASSY.

B4

WOOD

C1

METAL

C2

MAIN FAULT

Upper trigger not working. Trigger assembly & action
are covered with rust, dirt, and heavy sticky substance.
Ref. has been properly maintained.

PARTS

COMMENTS

Replace trigger assembly
& clean action at 1/2 normal cost
as you're to good with

Joel

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

FD6925 REV. 11

PPS 04686