tepair # : K12769 Received : 92/04/23 ilso See Repair # : ustomer : WM 813 Return Claim Number : 01-0813-727 Iddress : 315 A. EAST COMMERCE iddress : :ity, State Zip : BROWNWOOD, TX 76801 lake : REMINGTON Model : 700 ADL :al/Ga : 243 Serial # : C6279986 )ate to Factory : 92/06/30 Shipping Cost : 6.13 )ate Signed : F C # : D025 0908 317 F Sign : Factory Repair # : Date Returned from Factory : Date to Customer : Insured Value : 500.00 )ate AOD Signed : C C # : C Sign : Date of Inquiry : Person Inquiring : Jaiting Auth : Signer : Charges : Jaiting Parts : Part Numbers : Part Waiting On :

Jaiting On Response : Amount of Charges : Comments : STOCK CRACKED BY BOLT. ALSO FIRES ON CLOSING OF BOLT. WHEN BOLT CLOSES IT SOMETIMES RELEASES FIRING PIN CAUSING ACCIDENTAL DISCHARGE OF ROUND.

xplanation of Charges :

Serial Number Changed : Originally :

• • Tracer Information Date/Sent: Date/Received:

New :