

REPAIR GUN UPDATE FUNCTION: I (N)EXT (P)REV (U)PDATE (I)NQ (E)XACT 12/07/93  
ENTER REPAIR NUMBER -----> 9103643 10 57 55  
SERIAL NO: B6639409 NEW SERIAL NO: MODEL: 700  
FROM: (CUST NUM: 002719 ) AHLMANS GA/CAL: 0030-06  
AHLMANS TYPE: BDL  
RTE 1 BOX 20 ACCESSORIES: W/STUDS

MORRISTOWN MN 55052  
SHIPPED TO:

DATE CODES: EE 10-84  
OTHER ACCESSORIES:

COMMENTS:

DATES:	TO	FROM	
RECEIVED 01 29 91	GALLERY 00 00 00	00 00 00	ENTERED BY: LOS
OPENED 02 05 91	PROD SERV 00 00 00	02 15 91	REPAIRMAN: GH
ESTIMATED 02 20 91	TAG GUNS 00 00		TYPIST:
PROMISED 00 00 00	REJECTED 00 00		CORRESPONDENT:
GO AHEAD 00 00 00	CASH RECEIVED:\$	0.00	BILL TYPE: W
SHIPPED 05 13 91			
BILL TYPE INV PF1=VIEW DETAIL PF2=REPRINT R&E PF3=PRINT R&E PF5=CUST.MAINT			

REPAIR NUMBER: 9103643 REPR NOT AUTHORIZED WILM INVOICE PR 12/07/93  
CUSTOMER NAME: AHLMANS 10 58 00

=====

REQUEST: FIRED WHEN CLOSING BOLT, SAFETY STICKS  
FOR EVALUATION - SENT TO JIM STEKL

MAIN FAULT: NO FAULT FOUND - CAN NOT DUPLICATE COMPLAINT. TRIGGER AND  
SAFETY ASSEMBLY OPERATES PROPERLY. TRIGGER PULL 5 1/2 LBS.  
SEAR LIFT .015"  
DATE OF MFG:10/84

LABOR: \$ 0.00 RETURN AS RECEIVED NO REPLY AS OF 5/10/91  
\$ 0.00 GH;CM  
\$ 0.00 D/A0238875

REPAIRMAN'S INITS: GH NUM OF WKS: 06 CORRESPONDENT'S INITS:  
TOTAL VALUE:\$ 0.00 PF1 = INQ PF2 = ESTIMATE  
NO MORE DATA AVAILABLE FOR THIS REPAIR