

RECEIVING AND ESTIMATING REPORT

#33

DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	MODEL AND GRADE	ORDER
10/18/98	10/18/98	10/18/98	00224522	700-740	R
ACCESSORIES					

FROM:	SHIP TO:
IHERNLUND, MARTIN 201 FILBERT AVE ELSHIRE DE 19805	IHERNLUND, MARTIN 201 FILBERT AVE ELSHIRE DE 19805

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐	CLEAN/TEST	PROM. DATE	ESTIMATED	VIA	UPS
----------------	--------------------	--------------------------------	------------	------------	-----------	-----	-----

REPAIR CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL
---------------	-----	-----------	-----	-------------	-------

GUN CONDITION: ☐ NEW ☒ SLIGHTLY WORN ☐ VERY WORN ☐ MISUSED ☐ MARRED

CUSTOMER'S REQUEST

Sometimes rifle fires when safety is released; sometimes the firing pin will not cock, it simply follows the bolt down.

Trigger assembly rusted from some unknown source - internal parts not moving freely.

PARTS	Replace trigger assembly at no charge as gesture of good-will.

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE