

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER
R 94-14894

INITIAL

CUSTOMER ORDER NO.

ATTN: FRED MARTIN

FPS

DATE RECEIVED

DATE OPENED

DATE CODE

SERIAL NUMBER

NEW SERIAL NUMBER

MODEL AND GRADE

05/03/94

05/04/94

LQ 2-78

A6570501

700

7MM MAG

BDL

ACCESSORIES

W/STUDS

FROM:

SHIP TO:

TRI-STATE PLANT FOOD, INC.
HAROLD GRIFFIN
1615 E. BURDESHAW ST.
DOTHAN AL 36303

TRI-STATE PLANT FOOD, INC.
HAROLD GRIFFIN
1615 E. BURDESHAW ST.
DOTHAN AL 36303

CUST NO: 096881 G.L.O.B.

ACCOUNT NUMBER

ACCOUNT NUMBER W/C

WRITE ☐

FROM DATE

ESTIMATED

VIA

UPS

GUN CONDITION

- ☐ NEW
☐ LIGHTLY WORN
☐ WORN
☐ VERY WORN
☐ UNREPAIRABLE
☐ MARRED

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP		B2			E1	F1
BOLT ASSY.		B3			E2	F2
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

MAIN FAULT

W/ 1978 Unable to duplicate customer concern. Examination reveals that the bolt stop which would not retract, trigger pull measured at 2 1/2 lbs., and trigger adjustment seems have been a - none. During phone conversation with customer on 5/14/94, he stated he has never adjusted the trigger weight and that rifle was purchased new.

PARTS

COMMENTS

#26345
Checked trigger and action of rifle and to clean action & replace compressed trigger spring. Explained that normally there is a special repair cost when we find the rifle condition. Go ahead

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

RD6925 REV. 1/9