

RECEIVING AND ESTIMATING REPORT

DATE RECEIVED		DATE OPENED		DATE CODE		SERIAL NUMBER		MODEL AND GRADE		ORDER	
3-21-78		3-21-78		W-9-78		1042324		766 17		R 28-07-001	
CUSTOMER ORDER NO.		ACCESSORIES		TUBS		SCOPE					

FROM:	SHIP TO:
DALE TRUE RT. 1 LERDY KS 66856	DALE TRUE RT. 1 LERDY KS 66856

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE	PROM. DATE	ESTIMATED	UPSD
----------------	--------------------	-------	------------	-----------	------

REPAIR CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL
---------------	-----	-----------	-----	-------------	-------

GUN CONDITION: ☐ NEW ☒ SLIGHTLY WORN ☐ VERY WORN ☐ MISUSED ☒ MARRED

CUSTOMER'S REQUEST

"The rifle fires when you release the safety with the barrel pointing down"

MAIN FAULT

Connector is broken from pierced primers - Remington factory ammo being used.

PARTS

- 1) replace trigger assy. at No-charge*
- 2) Check firing pin / do in bolt for - replace bolt at No charge, if necessary.*
- 3) Complete repairs and return, do not charge 10.00 handling or return postage*
2/22/90
js.

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

RD6925 REV. 6/88