

RECEIVING AND ESTIMATING REPORT

INITIALS	CUSTOMER ORDER NO.	DATE RECEIVED	DATE ORDERED	DATE PAID	SERIAL NUMBER	MODEL AND GRADE	PRICE	ORDER
UJS		12/25/87	12/28/87	12/29/87	555134	7001-22-28		R
ACCESSORIES		SHIPPING BASE & DELIVERY CHARGES						

FROM	SHIP TO				
VERNON TUCKER 1200 OAK STREET BURNET TX 78611	VERNON TUCKER 1200 OAK STREET BURNET TX 78611				
ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE	FROM DATE	ESTIMATED	DATE
					UPS

REPAIR CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL

GUN CONDITION: ☐ NEW ☒ SLIGHTLY WORN ☐ VERY WORN ☐ MISUSED ☐ MARRED

CUSTOMER'S REQUEST

1) "This gun discharges when loading or unloading"
2) bolt face shows wear on closing bolt

1) no fault found - operates normally trigger pull 4 3/4#, S&W lift .006"
2) Extractor and rivet not set properly, replace extractor N/C

PARTS

Replace trigger assembly at N/C, per phone call to customer (same style safety - bolt lock)
2) Lubricate bolt lugs - slight galling.
Charge \$10.00 handling plus return shipping

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
J. E. S.					
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

RD5925 REV. 6/88