

PS 1616

RECEIVED

J.S.

FEB 11 1985

RECEIVED

J. A. STEKL

JAN 15 1985

CONSUMER SERVICE

January 19, 1985

Remington Arms Co., Inc.
939 Barnum Ave.
Bridgeport, Conn.

Dear Sirs:

Several years ago I bought a Remington Model 700 7M/M
Magnum. The caliber is excellent. However, I have
missed several nice bucks during the last three years
because of the mechanism of the rifle. On test runs
it works fine, but when I am out hunting, take careful
aim at a nice buck that comes along, and squeeze the
trigger, nothing happens. I check the safety and when
I push on the safety the gun goes off. Lucky Buck ...
ANGRY HUNTER!!!

I have taken the rifle to Bob Reynolds Gun Shop three
times. Each time they have said it was repaired.
It wasn't.

I don't expect you to repair the rifle, but I do expect
you to either tell me what is wrong with it so I can
have it fixed, or supply me with the name of a good
gunsmith who knows what he is doing. I would hate
to have to sell this rifle, because it is one of my
favorites.

Sincerely yours,

B. Y. Turner

Billy Y. Turner
720 Palestine Street
Jacksonville, Texas 75766

