

RECEIVING AND ESTIMATING REPORT			COMMENTS		ORDER R92-17175
INITIAL FPS	CUSTOMER ORDER NO.		ATTN: JIM STEKL W/BTM OF SCOPE MNTS		
DATE RECEIVED 08/27/92	DATE OPENED 08/27/92	DATE CODE LJ 2-89	SERIAL NUMBER C6340090	NEW SERIAL NUMBER	MODEL AND GRADE 700 270 WIN MNT
ACCESSORIES W/STUDS SCOPE BASE					

FROM: VELLUTINI, AL
281 MONTE VISTA AVE
HEALDSBURG CA 95448

SHIP TO: VELLUTINI, AL
281 MONTE VISTA AVE
HEALDSBURG CA 95448

CUSTOMER NO: 065457 C.O.D.

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐	CLEAN/TEST	PROM. DATE	ESTIMATED	VIA UPS
UN CONDITION						REPAIR CHARGE
☐ NEW						EXCISE
☐ LIGHTLY WORN						TAX
☐ WORN						INSURANCE
☐ VERY WORN						UPS
☐ UNREPAIRABLE						PARCEL POST
☐ MARRED						TOTAL

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
TRIGGER GROUP	A1	B1				
SLT ASSY.		B2		E2		F2
BREL ASSY.		B4		D1	E3	F3
EC ASSY.		B5		D2	E4	F4
MOD			C1	D3	E5	F5
TAL			C2			

NO FAULT
 Could not duplicate above complaint, however, the trigger
 situation is somewhat sticky and sluggish - investigation
 revealed issue of trigger assembly. The trigger assembly
 was removed of parts. This condition could cause the malfunction
 reported.

Trigger pull 5 1/2 pounds & over lift 0.135"

COMMENTS	
Replace trigger assembly at w/	
as a gesture of good will	
REPAIRMAN	PROOF
GALLERY TESTER	DATE
CLEAN	DATE
TEST	DATE
TARGET	DATE
PATTERN	DATE