

RECEIVING AND ESTIMATING REPORT

COMMENTS

Rec BAL of Arms 04-21-94

R

ORDER

94-11102

INITIAL CUSTOMER ORDER NO.

FPS V588424860

6788133

DATE RECEIVED

DATE OPENED

DATE CODE

SERIAL NUMBER

NEW SERIAL NUMBER

MODEL AND GRADE

03/25/94

03/28/94

DY 9-74

0473

700

30-06

B&L

ACCESSORIES

BOLT ONLY

w/ studs

scope base

FROM:

VAN FLEET, THOMAS L.
11640 N. PEARSON RD.
KELLER, TX 76248

SHIP TO:

VAN FLEET, THOMAS L.
11640 N. PEARSON RD.
KELLER, TX 76248

CUST NO 094951 G.O.B.

ACCOUNT NUMBER

ACCOUNT NUMBER NC

063103

SC.

WRITE

0

FROM DATE

ESTIMATED

VIA

3/29

UPS

GUN CONDITION

☐ NEW☐ LIGHTLY WORN☒ WORN☐ VERY WORN☐ UNREPAIRABLE☒ MARRED

REPAIR CHARGE 15.00

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

Send for bal of Arms

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	discharged when safety released				
TRIGGER GROUP		B1			E1	F1
BOLT ASSY.		B2			E2	F2
BARREL ASSY.		B3			E3	F3
REC. ASSY.		B4		D1	E4	F4
WOOD		B5		D2	E5	F5
METAL			C1	D3		
			C2			

MAIN FAULT

Upon receipt of the balance of the gun, we could not inspect customer
Comes. Inspection revealed a piece of old paper like material lodged behind the
portion of the gun safety lever. When closed, would block loading of shot and trigger
not trigger pull - 4 1/2 lbs. After pull 1000 lbs. pressure

PARTS

Gun left - .011
No 345 Trigger Assembly

COMMENTS

cannot check for a LL
Safety checks out OK. De gun
Replace complete trigger group and
then return at 1/2 normal adjustment and
test for good results
To return

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
FB.					
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 1/94

to A/S 5/19/94