

RECEIVING AND ESTIMATING REPORT ✓

INITIAL PS		CUSTOMER ORDER NO. 010065325RC		COMMENTS			
DATE RECEIVED 2/18/90	DATE OPENED 12/21/90	DATE CODE OF 7-85	SERIAL NUMBER B6731184	MODEL AND GRADE 700 270 WIN ADL		ORDER R 90-33598	
ACCESSORIES W/STUDS							

FROM:	SHIP TO:
WAL MART 65 HWY 66 & CUMBERLAND SULLIVAN MO 63080	WAL MART 65 HWY 66 & CUMBERLAND SULLIVAN MO 63080

COUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐	CLEAN/TEST	PROM. DATE	ESTIMATED	VIA UPS
--------------	--------------------	--------------------------------	------------	------------	-----------	------------

PAIR CHARGE						TAX	INSURANCE	UPS	PARCEL POST	TOTAL
-------------	--	--	--	--	--	-----	-----------	-----	-------------	-------

UN CONDITION:	☐ NEW	☐ SLIGHTLY WORN	☐ VERY WORN	☐ MISUSED	☐ MARRED
---------------	------------------------------	--	------------------------------------	----------------------------------	---------------------------------

CUSTOMER'S REQUEST

safety broken - fires when pushed off

MAIN FAULT

1) Seal engagement damaged with outside of factory - no engagement as received - sealant is not Remington sealant

2) Safety lever was removed from rifle outside of factory - incorrectly replaced - Detent ball and retainer spring missing

Safety is not broken, it is now incomplete!!

RTS

Sent repair quotation for new trigger assembly.

Product Service is retaining present assembly.

REPAIRMAN LEW	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 7/90

PPS 05281