

2. Be sure to return the complete rifle or complete barreled action, including the rifle bolt.
3. Include your name and return address on the outside of the package and on a note placed inside the box. Again, please remember to clearly label the outside package with DEPT. SST.

Should you need a box for shipping please call our 800 number and a shipping box will be provided.

Again, only a limited number of Model 700 Stainless Steel rifles are potentially affected. No other Remington gun models are involved.

Thank you for your cooperation in quickly resolving this important concern.

Sincerely,



K.A. Cornell, Supervisor
Special Services

KAC:tpp
encl.