

REPAIRING AND ESTIMATING REPORT

COMMENTS

W/OWNERS MANUAL

ORDER
R 94-00848

CUSTOMER ORDER NO.
811844

RECEIVED 06/94	DATE OPENED 01/07/94	DATE CODE PM 6-92	SERIAL NUMBER C6723382	NEW SERIAL NUMBER	MODEL AND GRADE 700 243	BDL/EUR.
-------------------	-------------------------	----------------------	---------------------------	-------------------	----------------------------	----------

ORIES W/STUDS

SHIP TO:

WALTER H CRAIG INC
BOX 557
NEW ORRVILLE RD
SELMA

AL 36702

WALTER H CRAIG INC
BOX 557
NEW ORRVILLE RD
SELMA

AL
36702

CUST NO:000015 WILM L

ITEM NUMBER	ACCOUNT NUMBER N/C 059001	WRITE ☐	FROM DATE	ESTIMATED 2-12	VIA UPS
-------------	------------------------------	--------------------------------	-----------	-------------------	------------

ADDITION
V ☒
HEAVILY WORN
RN
HEAVILY WORN
REPAIRABLE
BRED

REPAIR CHARGE
EXCISE
TAX
INSURANCE
UPS
PARCEL POST
TOTAL

OWNER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
---------------	------	----------	--------	----------	-----	---------

ER GROUP	A1	5				
SSY.		32			E1	F1
L ASSY.		B4		D1	E3	F3
SSY.		B5		D2	E4	F4
				D3	E5	F5
				C2		

ULT Upon receipt, unable to duplicate Customer concern. Inspection revealed
the trigger pull (5 lb) & reset (213) were within spec. Inspection
in May 1992. The only slightly non conforming item was that more than
one shot was required to cause the trigger assembly.

COMMENTS

Replace trigger assembly
at 11/92

REPAIRMAN BWT	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 1/92

PPS 05339