

IAL CUSTOMER ORDER NO.

W/MOZZEL FINISH  
W/MATT FINISH

DATE RECEIVED 9/10/93	DATE OPENED 09/14/93	DATE CODE EM 10-92	SERIAL NUMBER S6219886	NEW SERIAL NUMBER	MODEL AND GRADE 700 280 SS
ACCESSORIES W/STUDS					

DM:

WARREN, PHIL  
P O BOX 108  
HERMISTON

OR 97838

SHIP TO:

SHORT STOP #1  
CORNER OF PUMKIN CTR &  
DIAGONAL RD  
HERMISTON

OR

97838

CUST NO: 083478 C.D.D.L

COUNT NUMBER	ACCOUNT NUMBER NC	WRITE <input type="checkbox"/>	PROM. DATE	ESTIMATED	VIA UPS
--------------	-------------------	--------------------------------	------------	-----------	------------

IN CONDITION

NEW  
LIGHTLY WORN  
WORN  
VERY WORN  
UNREPAIRABLE  
MARRED

REPAIR CHARGE	25.00
EXCISE	
TAX	
INSURANCE	
UPS	
PARCEL POST	
TOTAL	

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
COLE	A1	B1				
HIGGER GROUP		B2			E1	F1
OLT ASSY.		B3			E2	F2
ARREL ASSY.		B4			E3	F3
EC. ASSY.		B5			E4	F4
OOD			C1	D3	E5	F5
ETAL			C2			

When accept rifle important. When change hit, bring in  
below down. Examination revealed that at 3 trigger adjustment seems  
how less triggered with more delay. And Red report found on all  
adjustment same.

Comments  
Replace trigger assembly  
at 1/2 normal adjustment cost, as  
gesture of good will.  
Go ahead

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 1/92

PPS 05347