

P.I. NO GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700 BDL

GENERAL CONDITION: NEW R #: 027181

OUTSIDE WORK: SCOPE MOUNTED DATE: 12-18-72

FROM: BRUCE WIGGINS
SPORTS SHOP

FIRE AMMO TYPE: - BEAUMONT, TEXAS

& CONDITION: _____ GUN #: 6418163

PROOF: R.E.P. INSP.: 73 TEST: 55 CODE: AU=3/71

HEADING: O.K. GR./CAL.: 17 REM.

BREECH OPENING: - CHECKED BY: C. PROSSER

RECOIL SHOULDERS: O.K. APPROVED: _____

CHAMBER: O.K. APPROVED: _____

TEST: NO APPROVED: _____

COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

SEAR-TRIGGER CONNECTOR ENGAGEMENT .010 (MIN. IS .020)

BURRS ON TRIGGER, SMALL BURR ON SEAR.

COMPLAINT: FIRES WHEN SAFETY IS RELEASED.

INCIDENT: FOLLOW DOWN.

COMMENTS: CUSTOMER'S MALFUNCTION NOT DUPLICATED.

APPARENTLY THE TRIGGER-SEAR BIND WAS ENOUGH

TO PREVENT RETRACTION INTO COCKED POSITION.