

4/26/64

94-13934

Pink colored sealant on overtravel
and pounds pull screw.

Sealant broke on rear engagement and
screw was turned in below surface of
trigger housing. not re sealed.

