

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER
R 94-13890INITIAL
FPS

CUSTOMER ORDER NO.

CALL TAG ATTN: DENNIS SANITA

DATE RECEIVED

DATE OPENED

DATE CODE

SERIAL NUMBER

NEW SERIAL NUMBER

MODEL AND GRADE

04/21/94

04/22/94

XS 12-69

6298777

700

308 WIN

BDL

ACCESSORIES

W/STUDS

SCOPE BASE

FROM

SHIP TO:

WHYMAN, WILLIAM
12335 CARON WAY
MADERA

CA 93638

WHYMAN, WILLIAM
12335 CARON WAY
MADERACA
93638

CUST NO: 096391 G.L.D.

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

WRITE ☐

FROM DATE

ESTIMATED

VIA

UPS

GUN CONDITION

- ☐ NEW
☒ LIGHTLY WORN
☐ WORN
☐ VERY WORN
☐ UNREPAIRABLE
☐ MARRED

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP		B2			E1	F1
BOLT ASSY.		B3			E2	F2
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.						
FOOD		C1		D3	E5	F5
METAL		C2				

MAIN FAULT

Upon receipt of the Ser. 1909 manufactured rifle, the trigger mechanism would not move manually or when fired. Examination revealed that trigger and housing were packed with heavy light grease which was not up to standard for the component. The action has received unit grease. Rifle now good working.

PARTS

COMMENTS

Repacked trigger assembly & clean action at 1/2 normal adjustment. Shot as positive of good work.

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

RD6925 REV. 1/94

PPS 05571