

RECEIVING AND ESTIMATING REPORT

COMMENTS

to Product Service

ORDER

R 94-08934

CUSTOMER ORDER NO.

L/ REAR SIGHT

DATE RECEIVED

DATE OPENED

DATE CODE

SERIAL NUMBER

NEW SERIAL NUMBER

MODEL AND GRADE

03/08/94

03/10/94

DI 9-76

A635999B

700 270

ACCESSORIES

L/MAG BOX

L/WOOD

L/FOLLOWER

L/MAG SPRING SCOPE BASE

OM:

SHIP TO:

YOUNGER, DON
37730 N VINTAGE DR
PALMDALE

CA 93550

YOUNGER, DON
37730 N VINTAGE DR
PALMDALE

CA

93550

CUST NO: 093876 C.D.DL

ACCOUNT NUMBER

ACCOUNT NUMBER NC

WRITE ☐

FROM DATE

ESTIMATED

VIA

UPS

IN CONDITION

NEW

LIGHTLY WORN

WORN

VERY WORN

UNREPAIRABLE

MARRED

AS Rec'd

normal

Twisted
in housing

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN

AMMO

FUNCTION

FINISH

ACCURACY

FIT

INSPECT

CLE

A1

B1

TRIGGER GROUP

B3

SLT ASSY.

B4

BREL ASSY.

B5

C. ASSY.

C1

D3

DOD

C2

ETAL

N FAULT

Gun Mfg. 9/76 Trigger bent as received, unable to determine if it was bent prior to return or in transit. Trigger is also twisted in housing probably from the same impact that bent it. Unable to make a proper evaluation due to above damage - exchange trigger assy as a gesture of good will.

COMMENTS

Trigger pull was 7# as rec'd
Sear lift measured .0095

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

RD6925 REV. 1/94

PPS 05636