


Serial
Number:

S6327873

Model: 700



RE00004263

As received gun would ~~to~~
fire on safe release because the
adjustment screws had been altered
to an unsafe condition.

Replace TPA * at 50% normal
costs.

FLS 2/17/00