

Remington.

TRACKING DOCUMENT

Repair Order Number



Repair Order Number RE00073058	Description/Serial Number ML073399	Repairman - Herb Brown
Account # - R-	Model 700ML Center Fire Caliber: 50 SS	Date Received - 11/17/2003
Customer A AND A SUPPLY 207 S MAIN ST P.O. BOX 1068 AMHERST. VA 24521 US		Estimate Date -
Phone (H) (434)-946-7668		Current Date - 11/20/2003
Phone (W)		Return To A AND A SUPPLY 207 S MAIN ST P.O. BOX 1068 OVID. NY 14521 US
	Fax	
	Email	

Reported		Found	
M992	FIRES WHEN SAFE RELEASED	M123	FORWARD TO PRODUCT SERVICE F

Material #		MaterialDesc	Quantity Needed	Quantity From Inv	Quantity From Kit	Warranty (Y/N)
Part						
F99294		700 ML SS TRIG ASSB	1	1	0	N
Part Total:			1	1	0	
Service						
4000104		ARMS SERV SHIPPING & HANDLING	0	0	0	N
Service Total:			0	0	0	

ProblemNotes All 3 adjusting screws re-set. Trigger connector broken. Bore action and trigger assm dirty. Replace trigger assm. at 50 % discount.

Repairman	Proof	Clean	Test	Target	
Gallery Tester	Date	Date	Date	Date	L

PS00231