

Repair Order Number



Repair Order Number RE00068095	Description/Serial Number G6218322	Repairman - Richard Hilts Date Received - 7/28/2003
Account # - R-	Model 700 Center Fire Caliber: 22 250 BDL	Estimate Date - Current Date - 8/7/2003
Customer A & C FIREARMS 5819 E US HWY 190 P.O. BOX 99 HEIDENHEIMER, TX 76533 US	Return To A & C FIREARMS 5819 E US HWY 190 P.O. BOX 99 HEIDENHEIMER, TX 76533 US	
Phone (H) (254)-983-4417 Phone (W)	Fax (254)-983-4528 Email archkoontz@aol.com	

Problems			
Reported		Found	
M992	FIRE WHEN SAFE RELEASED	M992	FIRE WHEN SAFE RELEASED

		Repair			
Material #	MaterialDesc	Quantity Needed	Quantity From Inv	Quantity From Kit	Warranty (Y/N)
Part					
F26345	700 TRIG ASSB RH	1	1	0	Y
Part Total:		1	1	0	
Service					
4000119	GR-TEST	1	1	0	Y
4000104	ARMS SERV SHIPPING & HANDLING	0	0	0	Y
4000118	GR-CLEAN	1	1	0	Y
Service Total:		2	2	0	

ProblemNotes	could not duplicate top of sear caked with foreign substance install new trigger clean action N/C under warranty FLS7/29/03				
Repairman	Proof	Clean	Test	Target	Pattern
Gallery Tester	Date	Date	Date	Date	Date