

Date: 2/27/04
By: Smith

FIREARM INSPECTION WORKSHEET

BACKGROUND

Customer name: Joe Helms

R.E. Number: 77874

Reason for inspection: Rifle found when safety was in operation

FIREARM

Manufacturer: Rem Model: 700

Serial Number: 66300928 Date of Manufacture: 2/03

Overall external condition: New

Barrel condition: _____

Receiver condition: _____

Stock condition: _____

Bolt/firing pin condition: _____

Trigger assembly condition:

Engagement: _____

Adjustments/alterations: _____

Other: big would not retract empty trigger & rust

Headspace: between chamber & trigger

Function evaluation: from warehouse owner

Feeding: _____

Extraction/ejection: _____

Trigger pull: 6 1/2 lbs

Manual safety: _____

Test firing results (if applicable): _____

DISPOSITION

Replace trigger assembly at no charge

ADDITIONAL COMMENTS

Upon receipt rifle inoperative, trigger would not retract