


Number: D6260935

Model: 700



RE00018707

Dave Cook PR

12/14/00

Sometimes goes off when safety is pushed
or bolt is brought home.

1007
4006
When revealed that the trigger adj &
stop screws have been re-set. Apparently
they have been backed out over 1/8" & re-set.

Replace trigger screw 1/2 MSP
GO ahead