

M/100 Lee Atkins Spt Shop

5/4/64

R-94-14821

Gun Goes off when releasing safety several times

- Unable to make gun malfunction as described or any other way, tried numerous times
- Trigger pull measured $4\frac{1}{2}\#$ to $4\#$
- Sen lift = .009
- trigger has been adjusted outside of factory
seal engagement (Red sealant)
and sounds pull no sealant
- Inside of trigger housing loaded with grease