

99736

July 26, 2005

To Whom It May Concern:

My Remington Model 700 Muzzle Loader will fire when you switch the safety from safe to fire. Please repair and return as soon as possible. I can be reached at 574-546-5828.

Sincerely,

Scott Allison

Scott Allison  
2970 Coffel Street  
Bremen, IN 46506

Could not duplicate. Sear  
movement sluggish. Install  
new TA N/C.

Charge 230145

FL8 8/17/2005

Serial Number: **ML241099**

Model: **700ML**

7/31/05



**RE00099736**

8/17/05