

RECEIVING AND ESTIMATING REPORT

COMMENTS

Potter

ORDER
R 93-11997

W/REDFIELD 2X7 SCOPE

INITIAL
JIMCUSTOMER ORDER NO.
7827DATE RECEIVED
05/18/93DATE OPENED
05/18/93DATE CODE
0D 7-83SERIAL NUMBER
7619151

NEW SERIAL NUMBER

MODEL AND GRADE
7 6MM

ACCESSORIES

W/STUFS

SCOPE MNTS

SCOPE BASE

L/SIGHTS

FROM:

AMBROSINO, ANTHONY
234 CO HWY 128
GLOVERSVILLE

NY 12078

SHIP TO:

AMBROSINO, ANTHONY
234 CO HWY 128
GLOVERSVILLE

NY

12078

CUST NO: 079256 C.O.D.L

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

WRITE ☐

PROM. DATE

ESTIMATED

VIA

DOOR

GUN CONDITION

- ☐ NEW
- ☐ LIGHTLY WORN
- ☐ WORN
- ☐ VERY WORN
- ☐ UNREPAIRABLE
- ☐ MARRED

DO NOT RETURN COD
NOTIFY CUST OF ANY
CHARGES
PER PHONE 5-24
P

REPAIR CHARGE 25.00

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN

AMMO

FUNCTION

FINISH

ACCURACY

FIT

INSPECT

CYCLE

A1

B1

TRIGGER GROUP

B2

E1

F1

BOLT ASSY.

B3

E2

F2

BARREL ASSY.

B4

E3

F3

REC. ASSY.

B5

D2

E4

F4

WOOD

C1

D3

E5

F5

METAL

C2

MAIN FAULT

Unable to duplicate customer concern. However, examination revealed that the trigger weight of gun has been set above minimum specification of 3 lbs., trigger adjustment screw has been backed out and the sealant removed, indicating it was required return to factory.

PARTS

COMMENTS

Bolt stop return jammed up
& working sluggish, action dropping
with subcompact
Trigger Pull - 1 1/2 lbs
Sensitivity - 0.12

Scope is in Cab.

Replace complete trigger assembly at
1/2 normal replacement cost and return
to factory of customer's gun will

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

RD6925 REV. 1/92

PS00532