

Date: 4/6/05

By: Bruce Travis SA

FIREARM INSPECTION WORKSHEET

BACKGROUND

Customer name: American Sportsman

R.E. Number: 95315

Reason for inspection: FBC Per Agreement to replace

FIREARM

Manufacturer: Rem. Model: 700

Serial Number: E6733761 Date of Manufacture: 5/01

Overall external condition: Good

Barrel condition: OKAY

Receiver condition: OKAY

Stock condition: OKAY

Bolt/firing pin condition: OKAY

Trigger assembly condition:

Engagement: —

Adjustments/alterations: —

Other: TRIG. + TRIG. PIN Rusty - BINDING TRIG.

Headspace: —

Function evaluation:

Feeding: _____

Extraction/ejection: _____

Trigger pull: 7.5th

Manual safety: 01044

Test firing results (if applicable): _____

DISPOSITION

Exchange for new R1A mac # 27357-NYC
change # 230145

ADDITIONAL COMMENTS