

Repair Order Number



Repair Order Number

RE00079865

Description/Serial Number

7648637

Repairman - Carl Cotton

Date Received - 4/15/2004

Account # - R-

Model 7 Center Fire Caliber: 7MM08

Estimate Date -

Current Date - 4/21/2004

Customer

AMERICAN SPORTSMAN INC
4088 WASHINGTON RD

Return To

AMERICAN SPORTSMAN INC
4088 WASHINGTON RD

MARTINEZ. GA 30907 US

MARTINEZ. GA 30907 US

Phone (H) (706)-863-4868

Fax (706)-863-1558

Phone (W)

Email

Reported		Problems	Found
M123	FORWARD TO PRODUCT SERVICE FOR INSPECTION	M174	BOLT STOP STICKS
M992	SOMETIMES FIRES WHEN TAKEN OFF SAFE	M178	TRIG ADJ SCREWS RESET, CANNOT

Material #		MaterialDesc	Quantity Needed	Quantity From Inv	Quantity From Kit	Warranty (Y/N)
Part						
F92458	7	TRIGGER ASSB	1	1	0	N
Part Total:			1	1	0	
Service						
4000104		ARMS SERV SHIPPING & HANDLING	0	0	0	N
4000118		GR-CLEAN	1	1	0	N
4000119		GR-TEST	1	1	0	N
4000294		GR-CHECK TPA	1	1	0	Y
Service Total:			3	3	0	

Condition

fair

ProblemNotes

The action and trigger assy. are coated with a sticky lubricant. Cleaning and installing a new trigger assy. at 1/2 MSP

Repairman	Proof	Clean	Test	Target	Pattern
Gallery Tester	Date	Date	Date	Date	Date