

Serial
Number:

G6215504

Model: 700



RE00057212

12/16/02

BW
1/02

Upon receipt could not duplicate the reported
Concern - tug vacuum disassembled nothing
found out explanation

Agreed to replace

Supply replacement M/700 ADL 270 (7476)
New # _____

in shipping
Charge 230145

Replace tug vacuum in ser# G6215504 & send to WIP Sub