

Remington.

Factory Repair Instructions

(NOTE: Please print and complete this form, and then include it with your firearm.)

Model Number: 700-30-06 Serial Number: B6786815

Are you the original owner?: ☐ YES ☒ NO

Name: Bruce Anderson Date of Purchase:

Address (no PO Boxes):

110 General Knox Rd

City: Russell

State: MA

Zip: 01071

Phone (Daytime): 413-568-7391 Fax:

E-mail Address: BAnderson1240@AOL.COM

☒ I would like to receive future e-mail updates from Remington.

Please describe your problem:

Gun will fire when safety is pushed off, without finger anywhere near trigger. Please see if there is a need for a bolt lock safety modification

(not duplicate concern)

Ammunition Information:

Manufacturer:

Type: Altered Adjustments and sticky residue. install

Other (i.e. bullet weight/type, shot size, powder):

new TA clean seton - charge customer \$20.00

Handload Information:

Powder Used:

Powder Weight:

Case/Hull Used:

Primer Used:

Bullet Type/Shot Size:

Reloader Used:

Firearms Care (Cleaning and Lubrication):

B6786815

Model: 700



RE00050540

of rounds)

of rounds)

or Number of rounds)

er of rounds)

nber of rounds)

ths or Number of rounds)

Have you reviewed the cleaning and maintenance recommendations on our web site or in our owners

manual? ☐ YES ☐ NO

<http://www.remington.com/support/repairsvc/FACTREP.HTM>

7/31/02