

Remington

TRACKING DOCUMENT



Repair Order Number

Repair Order Number RE00077005	Description/Serial Number 81172	Repairman - Chuck Dekanek Date Received - 2/18/2004
Account # - R-	Model 721 Center Fire Caliber: 3006	Estimate Date - 2/12/2004 Current Date - 2/26/2004
Customer ERIC ANDERSON 16 NORTHERN HEIGHTS DRIVE WINCHENDON, MA 01475 US		Return To ERIC ANDERSON 16 NORTHERN HEIGHTS DRIVE WINCHENDON, MA 01475 US
Phone (H) (978)-297-1536 Phone (W) (978)-621-4477 XC		Fax Email

Reported	Problem	Found	
M240	BOLT LOCK SAFETY MODIFICATION	M993	FORWARD TO PRODUCT SERVICE F
M992	SEND TO PRODUCT SERVICE FOR EVALUATION		
M993	ACCIDENTAL DISCHARGE		

Material #	MaterialDesc	Quantity Needed	Quantity From Inv	Quantity From Kit	Warranty (Y/N)
Part					
F26345	700 TRIG ASSB RH	1	1	0	Y
Part Total:					
Service					
4000104	ARMS SERV SHIPPING & HANDLING	0	0	0	Y
4000116	GR-LABOR	20	20	0	N
4000119	GR-TEST	1	1	0	Y
4000294	GR-CHECK TPA	1	1	0	Y
Service Total:					
		22	22	0	

Problem/Notes		Check safety. Upon receipt we could not duplicate accidental discharge when closing or opening the bolt assem. Trigger adjustment and stop screws back out. DJS 2/12/04 MFG 1949			
Repairman	Proof	Clean	Test	Target	Pattern
Gallery Tester	Date	Date	Date	Date	Date