

Repair Order Number



Repair Order Number RE00073742	Description/Serial Number 6436170	Repairman - Bruce Travis
Account # - R-	Model 700 Center Fire Caliber: 6 MM	Date Received - 12/5/2003
	BDL	Estimate Date -
		Current Date - 12/12/2003
Customer BOBBY ANDREWS 119 S W MAIN ST P.O. BOX 54 ELDORADO, TX 76936 US		Return To BOBBY ANDREWS 119 S W MAIN ST P.O. BOX 54 ELDORADO, TX 76936 US
Phone (H) (325)-853-2452 XHM		Fax
Phone (W) (325)-277-4140 XCELL		Email

Reported	Problem	Found
M992	HI PRESSURE	M123
		FORWARD TO PRODUCT SERVICE F

Material #	MaterialDesc	Quantity Needed	Quantity From Inv	Quantity From Kit	Warranty (Y/N)
Part					
F26345	700 TRIG ASSB RH	1	1	0	Y
F26370	700 TRIG GUARD ASSEMBLY S/A	1	1	0	Y
F28711	700 BOLT ASSB S/A CS F1	1	1	0	Y
F93712	700 EXTRACTOR REG (7400;710)	1	1	0	Y
F94555	700 EJECTOR PIN (SPIROL)	1	1	0	Y
Part Total:		5	5	0	
Service					
4000119	GR-TEST	1	1	0	Y
4000104	ARMS SERV SHIPPING & HANDLING	0	0	0	Y
4000117	GR-PROOF	1	1	0	Y
Service Total:		2	2	0	

ProblemNotes	mfg date 5/71 bolt face damaged and trigger guard broken - leaky primers. repair at no charge. new bolt will not match to old trigger assm, will replace with new style trigger assm				
Repairman	Proof	Clean	Test	Target	Pattern
Gallery Tester	Date	Date	Date	Date	Date