

Arms Service Divisions:

This box contains 2 model 700 BDL's. The right handed 700 has a broken stock. The left handed 700 was a recall gun for the trigger mechanism (sometimes it goes off by itself) & the stock is cracking in the same place as the other. Both guns are unloaded! If there is a problems I can be reached at (318) 574-4903.

API outdoors
C/O Greg Davis
6002 Kimbrough DR.
Tallulah, LA. 71282