

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER

R 97-19725

INITIAL

CUSTOMER ORDER NO

PRODUCT SERVICE

DATE RECEIVED

DATE OPENED

DATE CODE

SERIAL NUMBER

NEW SERIAL NUMBER

MODEL AND GRADE

11/13/97

11/14/97

WU 8-71

6471065

700 30-06

BDL

ACCESSORIES

W/STUDS

SCOPE BASE

L/SIGHTS

FROM:

ARMANINO GUN SHOP
329 GRAND AVE
SO SAN FRANCISCO

CA 94080

SHIP TO:

ARMANINO GUN SHOP
329 GRAND AVE
SO SAN FRANCISCOCA
94080

CUST NO: 000230 C.O.D.

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

WRITE ☐

PROM. DATE

EST. MATED

VIA

UPS

GUN CONDITION

- ☐ NEW
☐ LIGHTLY WORN
☐ WORN
☐ VERY WORN
☐ UNREPAIRABLE
☐ MARRED

REPAIR CHARGE 28.00
EXCISE
TAX
INSURANCE
UPS 8.00
PARCEL POST
TOTAL 36.00

CUSTOMER CONCERN

AMMO

FUNCTION

FINISH

ACCURACY

FIT

INSPECT

CYCLE

TRIGGER GROUP

BOLT ASSY.

BARREL ASSY.

REC. ASSY.

WOOD

METAL

MAIN FAULT

Trigger Assy has failed, gun damaged
when closing the bolt

Rifle Mfg 1971 - upon receipt we could not duplicate the
reported concern, but did find the bolt stop valve seized up, and
found the trigger housing covered with a heavy sticky substance.

Part was also noted on the trigger & gun. The trigger Assy. & stop
valve have been replaced. The action runs smoothly. Rifle properly
maintained.

#26345

Replace the complete trigger
Assy. & clean the action at
1/2 the normal cost

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

PS00748