

FACTORY SERVICE
MODEL 700 # B6782962
MOUNTAIN RIFLE

AFTER OPERATING THE
BOLT THE TRIGGER DOES
NOT FIRE THE BOLT
ALSO ON CERTAIN
OCCASSIONS WHEN
ATTEMPTING TO OPERATE
THE BOLT AGAIN IT
WILL FIRE UPON
LIFTING THE BOLT

Return
Address

ARMY SURPLUS I
501 Oak Street
Sandpoint, ID 83864
(208) 263-7331