

Repair Order Number



Repair Order Number RE00051261	Description/Serial Number A6529788	Repairman - Dale Lewis Date Received - 8/29/2002
Account # - R-	Model 700 Center Fire Caliber: 223 VARMINT	Estimate Date - 8/28/2002 Current Date - 9/4/2002
Customer MIKE ARRENDELL 90 N FOREST COVE LOOP COLDSPRING, TX 77331 US		Return To MIKE ARRENDELL 90 N FOREST COVE LOOP COLDSPRING, TX 77331 US
Phone (H) (281)-821-1144 Phone (W)		Fax (281)-821-5155 Email parts@monkeng.com

Reported	Problem	Found	
M123	FORWARD TO PRODUCT SERVICE FOR INSPECTION	M123	FORWARD TO PRODUCT SERVICE F
M993	WEAPON FIRES WHEN YOU CLOSE THE BOLT		

Material #	MaterialDesc	Quantity Needed	Quantity From Inv	Quantity From Kit	Warranty (Y/N)
Part					
F26345	700 TRIG ASSB RH	1	1	0	Y
Part Total:		1	1	0	
Service					
4000119	GR-TEST	1	1	0	Y
4000104	ARMS SERV SHIPPING & HANDLING	0	0	0	Y
4000116	GR-LABOR	20	20	0	N
Service Total:		21	21	0	

ProblemNotes altered adjustments and broken connector-install new ta and clean action quote \$20 under bolt lock mod program per orod service					
Repairman	Proof	Clean	Test	Target	Pattern
Gallery Tester	Date	Date	Date	Date	Date


12 LBS 1 OF 1

REMINGTON ARMS CO INC
800 243-9700
14 HOEFLER AVE
MILTON NY 13357

SHIP

TO:

MIKE ARRENDELL
90 N FOREST COVE LOOP
COLDSRING TX 77331




TX 773 0-02



UPS GROUND

TRACKING #: 1Z 114 813 03 1193 7689



BILLING: P/P

INV#: RE00051261

ASC 05.00 J69X/J64X 16.0A 01/2002