Remington

Repair Form

(NOTE: Please print and complete this form, and then include it with your firearm.)

Model Number: MDL - 700

Serial Number: *A6529788*

Name: Mike Arrendell

Date of Purchase: 8-1202

Address (no PO Boxes)::

90 N. Forest Cove Loop

City: Cold Spring

State: TX

Zip: 7733)

Phone (Daytime): 28/- 82/- 1/44

Fax: 28/-821-5155

E-mail Address: PATTS @ MONKENG. COM

Please describe your problem: WEAPON FIRE'S When

You Close The Bolt.

BO - 1/78

51261

Additional Information: (Ammo type, brand, handload specifications, etc.) Follows Nown - Altens ad

and hoken connector-

install new TA and

clean Action. Quote 2

\$20.00 under b

Modification program -

FLS 8/28/02

NOTE: Prior to shipping your firearm, contact the Repair Center for services provided and estimated repair time.

WARNING: DO NOT SEND LIVE OR SPENT SHELLS IN YOUR FIREARM OR IN THE SAME BOX WITH THE FIREARM. **THIS IS A VIOLATION OF FEDERAL LAW.** IF YOU FEEL YOU MUST SEND SPENT SHELLS PLEASE SEND THEM IN A SEPARATE PACKAGE AND INCLUDE NAME, ADDRESS (WITH ZIP CODE), TELEPHONE AND MODEL AND SERIAL NUMBER OF YOUR FIREARM.

A6529788

before sending it.
Int further damage in shipping and

Model: 700

tes may not be returned.)

1 to prevent loss or damage.

S or Parcel Post. Remington is not



orm.htm

7/29/02