



☒ 944 Bonifant St.
Silver Spring, Md. 20910

☐ 601 Hungerford Dr.
Rockville, Md. 20850

(301) 585-4448
Fax (301) 585-5935

(301) 279-7983
Fax (301) 279-0256

TO

Remington Factory Repair
14 Hoefler Ave.
Ilion, NY 13357

DATE 9-17-01

SUBJECT

700
#E6693006
w/Scope Bases

The Owner of this rifle is adamant that he had an unexpected discharge when disengaging the Saffy. I disassembled the rifle's fire control system and found nothing wrong. Please inspect & Correct any problems you may discover.

Thanks,
Walt.

No Fault Found
Install new TA MC as gesture of goodwill
to restore customer's faith in rifle.
FLS 9/21/01

☒ PLEASE REPLY ☐ NO REPLY NECESSARY

Serial Number:

E6693006

Model: 700



RE00032805