

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER
R 93-09811

IAL JM	CUSTOMER ORDER NO.	W/BUSHNELL SPORTVIEW 4X32 SCOPE			
DATE RECEIVED 4/12/93	DATE OPENED 04/14/93	DATE CODE LW 2-72	SERIAL NUMBER 6526682	NEW SERIAL NUMBER	MODEL AND GRADE 700 270
ACCESSORIES L/WOOD		SCOPE MNTS		SCOPE BASE	

POTTER

1. Setup file

2. XC F. Supply

NAME BRAINARD, ROGER MCGREGOR GUNSMITH 910 W MAIN RR MCGREGOR	SHIP TO: BRAINARD, ROGER MCGREGOR GUNSMITH 910 W MAIN RR MCGREGOR
IA 52172	IA 52172

COUNT NUMBER	ACCOUNT NUMBER N/C	PROM. DATE	ESTIMATED 4/22/93	VIA UPS
CONDITION		REPAIR CHARGE		
NEW		EXCISE 25.00		
LIGHTLY WORN		TAX		
WORN		INSURANCE		
VERY WORN		UPS		
UNREPAIRABLE		PARCEL POST		
MARRED		TOTAL		

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CLE	A1	B1				
TRIGGER GROUP		B2			E1	F1
LT ASSY.		B3			E2	F2
RREL ASSY.		B4		D1	E3	F3
C. ASSY.		B5		D2	E4	F4
MOD			C1	D3	E5	F5
TAL			C2			

"Trigger off under safety is moved"

Unable to cycle in action
Action Components disassembled. Trigger assembly also removed from
Trigger Assembly. Trigger Adjustment screws tightened with outside pliers.
Trigger Reset lever removed.

ITS	COMMENTS
	Reassemble trigger assembly at 1/2 normal adjustment level.
	Clean action, reassemble components of ahead

REPAIRMAN 232	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 1/92