

CEIVING AND ESTIMATING REPORT

COMMENTS

R ORDER
77-25551

CUSTOMER ORDER NO.

Product
Service

RECEIVED 12/22/93	DATE OPENED 12/02/93	DATE CODE PY 6-79	SERIAL NUMBER A6786035	NEW SERIAL NUMBER	MODEL AND GRADE 700 30-06	BDL
SERIES W/STUDS						

SHIP TO:

BAYVILLE SPTG GOODS INC
259 BAYVILLE AVE
BAYVILLE

NY 11709

BAYVILLE SPTG GOODS INC
259 BAYVILLE AVE
BAYVILLENY
11709

CUST NO: 011859 C.O.N.

JNT NUMBER	ACCOUNT NUMBER N/C	PROM. DATE	ESTIMATED 12/16/93	VIA R640479752
WRITE ☐				

CONDITION	REPAIR CHARGE 25.00
EW	EXCISE
3HTLY WORN	TAX
ORN	INSURANCE
ERY WORN	UPS
REPAIRABLE	PARCEL POST
ARRED	TOTAL

FORMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
----------------	------	----------	--------	----------	-----	---------

E						
---	--	--	--	--	--	--

3ER GROUP						
-----------	--	--	--	--	--	--

ASSY.						
-------	--	--	--	--	--	--

REL ASSY.						
-----------	--	--	--	--	--	--

ASSY.						
-------	--	--	--	--	--	--

D						
---	--	--	--	--	--	--

L						
---	--	--	--	--	--	--

FAULT						
-------	--	--	--	--	--	--

Upon receipt, unable to duplicate Customer Concern. However
examination reveals that the bolt stop release and other safety items are
being shipped from the factory and trigger assembly being covered with safety
sealant. Refs mfg 1979

COMMENTS

Refers complete trigger assembly &
clean action at 1/2 normal cost,
as per spec of good unit

REPAIRMAN JTB	PROOF	CLEAN ✓	TEST ✓	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 1/92

PS00946