

Remington.**REMINGTON ARMS COMPANY, Inc.**SPORTING FIREARMS, AMMUNITION, TARGETS AND TRAPS
ILION, NEW YORK 13357PAGE 1
QUOTATION
LOADING SAVER

DATE:

12/07/92

PARTS (315) 895-7493
REPAIR (315) 895-7791
FAX (315) 895-7214 (315) 895-3059
CUSTOMER NUMBER: 257

SOLD TO

REPAIR ORDER NO.: 92-24328

SHIPPED TO

REPAIR ORDER NO.

FRONTIER GUN SHOP
14115 E LANDELT ST
WHITTIER CA 90605FRONTIER GUN SHOP
14115 E LANDELT ST
WHITTIER CA 90605

THIS IS AN ESTIMATE TO REPAIR, RECONDITION OR REPLACE THE ITEM(S) DESCRIBED BELOW. IF THIS IS SATISFACTORY, PLEASE APPROVE BY SIGNING BELOW. RETURN THE FIRST COPY TO REMINGTON ARMS CO. INC. ILION, NY 13357. KEEP THE SECOND COPY AS YOUR RECEIPT.

REPAIR TO TAKE ABOUT 5 WEEKS AFTER RECEIPT OF APPROVAL. IF WE DO NOT RECEIVE YOUR APPROVAL IN THIRTY DAYS, WE SHALL RETURN THE ITEM(S) AS RECEIVED.

700 30-06 DDL/LH SERIAL NUMBER: 6720579
H/STUDS SCOPE BASE L/SIGHTSCUSTOMER REQUEST:
BROKEN CONN.

MAIN FAULT FOUND:

AS ABOVE

REPLACE TRIGGER AT 1/2 PRICE AS PER PRODUCT SERVICE

NO OTHER FAULTS FOUND

DATE OF MFG: 04-73

1 0020345 TRIGGER ASSEMBLY KH
9900005 TEST

24.00

5.00

WE ARE OFFERING TRIGGER ASSEMBLY AT 1/2 NORMAL COST,
AS GESTURE OF GOOD-WILL -
PD/HAK**ALL PRICES QUOTED ARE IN EXCHANGE FOR REPLACED PARTS**TOTAL REPAIR CHARGE
TAXES

29.00

☐ PLEASE RETURN REMITTANCE
WITH THIS COPY OR SHIPMENT
WILL BE MADE C.O.D.NOTE: IF YOU DESIRE ANY CHANGE USE THE
REVERSE SIDE FOR YOUR COMMENTS
AND MARK THIS BLOCK. ☐INSURANCE
PARCEL POST

3.00

PLEASE CIRCLE ONE
CARD
VISA/MC NO.EXP.
DATEDAYTIME
PHONE NO.TOTAL
CHARGES

34.00

THIS IS AN ESTIMATE TO REPAIR OR RECONDITION THE ITEMS LISTED
ABOVE. IF SATISFACTORY, PLEASE SIGN AND RETURN THIS COPY
TO:
REMINGTON ARMS COMPANY, INC.
ILION, NEW YORK 13357

CUSTOMER'S SIGNATURE